


Mufă PPR egală - ALBĂ, Lipire x Lipire


PPR Socket, Welding x Welding



COD	Dimensiune	$\varnothing d1$	L	E	Ambalaj
0311021	20x20	19,5	34	14,5	280
0311022	25x25	24,5	37	16	180
0311023	32x32	31,5	41	18	108
0393301	40x40	39,4	45	20,5	60

Mufă PPR redusă - ALBĂ, Lipire x Lipire


PPR Reducing Socket, Welding x Welding



COD	Dimensiune	$\varnothing d1$	$\varnothing d2$	E1	E2	L	Ambalaj
0311031	25x20	24,5	19,5	16	14,5	35	280
0311032	32x20	31,5	19,5	18	14,5	38	180
0311033	32x25	31,5	24,5	18	16	40	108
0311327	40x32	39,4	31,5	20,5	18	47	60

Reducție PPR - ALBĂ, Lipire x Lipire

PPR Reducer, Welding x Welding



COD	Dimensiune	$\varnothing d1$	L	E	D	Ambalaj
0311004	25x20	19,5	39	14,5	25	250
0311005	32x20	19,5	39	14,5	32	180
0311006	32x25	24,5	43	16	32	120
0311007	40x25	24,5	43	16	40	100
0311008	40x32	31,5	48	18	40	105