


Adaptor PPR - ALB, Lipire x FI


PPR adaptor, Welding x F



COD	Dimensiune	Ø d1	L	E	Ambalaj
0311041	20x1/2"	19,5	40	14,5	150
0311042	20x3/4"	19,5	40	14,5	120
0311043	25x1/2"	24,5	43	16	120
0311044	25x3/4"	24,5	43	16	105
0311045	32x3/4"	31,5	44	18	48
0311046	32x1"	31,5	44	18	48

Adaptor PPR - ALB, Lipire x FE


PPR adaptor, Welding x M



COD	Dimensiune	Ø d1	L	E	Ambalaj
0311051	20x1/2"	19,5	55	14,5	140
0311052	20x3/4"	19,5	55	14,5	90
0311053	25x1/2"	24,5	57	16	120
0311054	25x3/4"	24,5	57	16	90
0311055	32x3/4"	31,5	60	18	48
0311056	32x1"	31,5	60	18	48

Racord PPR cu semiolandez , Lipire x FI

PPR nipple with nut, Welding x F



COD	Dimensiune	Ø d1	E	Ambalaj
0311415	20x1/2"	19,5	14,5	120
0311416	25x3/4"	24,5	16	60