


Racord olandez PPR, Lipire x FI


PPR Transition Union, Welding x F



COD	Dimensiune	Ø d1	L	E	Ambalaj
0311071	20x1/2"	19,5	38	14,5	160
0311072	25x3/4"	24,5	38	16	90
0311073	32x1"	31,5	42	18	60
0393305	40x1 1/4"	39,4	48	20,5	30

Racord olandez PPR, Lipire x FE


PPR Transition Union, Welding x M



COD	Dimensiune	Ø d1	L	E	Ambalaj
0311061	20x1/2"	19,5	45	14,5	120
0311062	25x3/4"	24,5	49	16	80
0311063	32x1"	31,5	52	18	48
0393304	40x1 1/4"	39,4	59	20,5	24

Racord olandez PPR, Lipire x Lipire

PPR Transition Union, Welding x Welding



COD	Dimensiune	Ø d1	E	L	Ambalaj
0312061	20x20	19,5	14,5	56	
0312062	25x25	24,5	16	59	
0312063	32x32	31,5	18	60	